



GOOD COUNSEL SCHOOL

Rankin St INNISFAIL QLD

Project Overview

The project involved major structural repairs to the Primary and Upper School along with the Church and surrounding buildings located onsite at Mother of Good Counsel in Innisfail North Queensland. Hutchinson Builders' expertise was called upon following the aftermath of the devastating Cyclone Larry in March 2006. Works commenced in April of 2006 with priority given to making the site as safe as possible for a quick return to school by the staff and students. Working with the clients' insurers to develop an accurate scope of work and provide budget pricing on various elements onsite work was expedited wherever possible. Major re-building of the Primary School Junior Block saw a complete refurbishment exercise take place with a new upper floor re-built. Other works completed included refurbishment of the performing arts building, various classroom repairs and upgrades, mechanical plant and equipment upgrades, large scale re-roofing, external works including re-turfing and major refurbishment works to the Church.

